













- 2015: 9 Part A's Total, 2 for NOx, 3 for Mill particulates, 4 fugitive Dust.
- 2016 YTD: 3 Part A's all for Main stack Dust (11.3, 12.8 & 11.8mg/Nm³ against limit of 10mg/Nm³)



- 2015 complaint Review: 54 contacts to site:
 - 40 for dust, 25 could be linked to site, having a significant proportion of cementitious materials present.
 - Investigations on site could not initially link these to a specific emission event however a detailed review of the cooler filter/heat exchanger operation showed a causal link between increased dust complaints containing clinker and the rise in emissions from the filter.
 - The heat exchanger was replaced during the January-February Shut down and work completed on the associated filter to reduce the impact of the operation of this equipment.






■ 2015 complaint Review:


- 8 contacts for noise in 2016, for 5 of which the site could not be ruled out as the cause.
- 3 odour, 2 not related to site, one was probably a very rare plume grounding event in a non prevailing wind direction.
- 3 for visible plume


■ 2016 YTD:

- 5 for noise, 1 caused by works within the Preheater tower during shutdown, complainant contacted directly and given information as to cause.
- 4 further complaints (3 from same address) being investigated as currently the site cannot be definitively ruled out.









- Since Last Meeting:
 - Alun School STEM Scholarship 2 students been chosen for 2016,

- Visits to site:
 - Visit from Chester U3A Industrial interest group.

